

### United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office
Address: COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450
www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
09/975,386	10/11/2001	Kenneth David Knapp	24-01	1255
27569	7590 03/28/2006		EXAMINER	
PAUL AND PAUL			A, PHI DIEU TRAN	
2000 MARKET STREET SUITE 2900			ART UNIT	PAPER NUMBER
	HIA, PA 19103	3637		
			DATE MAILED: 03/28/2006	

Please find below and/or attached an Office communication concerning this application or proceeding.



# UNITED STATES DEPARTMENT OF COMMERCE

U.S. Patent and Trademark Office

Address: COMMISSIONER FOR PATENTS P.O. Box 1450

Alexandria, Virginia 22313-1450

APPLICATION NO.I CONTROL NO.	FILING DATE	FIRST NAMED INVENTOR I PATENT IN REEXAMINATION		ATTORNEY DOCKET NO.
09/975, 386				
			EXAMINER	
			ART UNIT	PAPER

DATE MAILED:

Please find below and/or attached an Office communication concerning this application or proceeding.

**Commissioner for Patents** 

032206

The reply brief filed 1/17/2006 has been entered and considered. The application has been forwarded to the Board of Patent Appeals and Interferences for decision on the appeal.

PH 3/22/06

LANNA MAI SUPERVISORY PATENT EXAMINER TECHNOLOGY CENTER 3600

PTO-90C (Rev.04-03)



JAN 17 2006

## THE UNITED STATES PATENT AND TRADEMARK OFFICE

**PATENT** 

OK to chi o s

Serial No.:

09/975,386

Filed:

October 11, 2001

For:

Insulation Blanket With Cut Guidelines

Inventors:

Kenneth D. Knapp

Examiner:

A, Phi Dieu Tran

Art Unit:

3637

Atty. Doc. No.: 024-01

#### SUPPLEMENTAL REPLY BRIEF

Mail Stop Appeal Brief Patents Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

### THE EXAMINER'S ANSWER LACKS CREDIBILITY

The Examiner's Answer, on page 4, five lines from the bottom states that:

Ernest (figure 2) shows a blanket of fibrous building insulating... (sic)

That statement is flatly untrue. Ernest shows a "forced gas appliance" with insulation in it [col. 2 L. 42-51]. It has absolutely *nothing* to do with a *building*.

The Examiner's Answer states at page 4, 5 lines from bottom and page 5 lines 5-

6:

Ernest (figure 2) shows... spots of adhesive visible through the perforations at the second sheet surface of the facing sheet...